

# *Bally* DISTRIBUTING COMPANY

390 EAST SIXTH STREET • POST OFFICE BOX 6418 • RENO, NEVADA 89513  
TELEPHONE AREA CODE 702 • 323-6156 • TELEX 35-4414 • CABLE BALDISCO

## B U L L E T I N

We have found that a possible malfunction in the pay circuit could arise on Models 1090 and 1090-1 due to a slight maladjustment of the reel wiper arms. The following simple rewiring modification on Reel Card #2 should correct the problem:

Remove 98 Jumper from Row #4 Depth #5 counting from top of reel card - put it on Row #8 Depth #5.

Remove 71 Jumper from Row #5 Depth #5 - put it on Row #9 Depth #5.

Cut Wiper two blades from bottom as indicated on attached drawing.

If you have any questions, please contact Stan Smith in our Reno Shop, 323-6156.



Bob Weiss  
General Manager  
BALLY--Reno

10/19/77

